## alignment status as of January 2006

## development of a calibrating procedure (DM)

- misalignment by shifting hits
- residuals taken from TRDdebug.root
- the observed position resolution is reasonable
- the observed shift of residuals is too small (probably because the TRD is used in tracking)
- private version of TRD software from CVS for modifying and debugging
- do not use TRD in tracking
- standalone TRD tracking

## proper implementation of geometry

 overlap problem, not quite decided that we really want it, Jan Fiete enough work implementing calibration parameters → not yet really started