


P1

Gamma3

This part goes into the wall/collimator



					Datum	Name							
					Gezeichnet	6/11/2012						bloehner	
					Kontrolliert								
					Norm								
								Beam Pipe Metal Part					
Status	Anderungen	Datum	Name										
									1				
									A2				